PHA Page 1 of 3

Inside Home Find & Search

People Finder

## **PHA Findings**

PHA Database | PSM Home | LC, Seismic & ISS Findings



## | PHA Search | PHA Results | Employee Feedback | Print this page |

ABU	Plant	Revalidation	Start Date	End Date	Facilitator	Scribe			
D&R	#5 Rheniformer	2nd Revalidation	10/5/2006	10/10/2006	Tim Storrs				
Core Team	Members / Role		Close Out Meeti	Close Out Meeting Participants / Role					
	perations; Dan Matson - Process I In Post - Designs Engineering	Engineering; Brian Scaief - Designs	Carl Simmers - ABU	Carl Simmers - ABU Manager; Michelle Capshaw - D&R Section Head					
Additional P	articipants / Role		Entire PHA Repo	Entire PHA Report					
			\\ric841ntshare1\sh	$\label{links} $$ \operatorname{Links}_2006\ 4\&5\ Rhen\ PHA.pdf = \label{links} $$$					
				* Further discussion about any portion of the report and its contents should be directed to the facilitator or any of the team members listed					
Comments									
Reviewed B	y Date Feedbac	ck/Comments							

Section No Section Description										
45		NAPHTHA thru static mixer, E-580 to V-580 including Regenerator Wash and K-550 Anti-surge								
Item	WhatIf	Deviation	A/C	SOE	RR	ABU Proposal	Resolution	Owner	Due By	Status
4	16391	Mis-Directed Flow	Consider providing additional training for PCOs and outside operators on the Trisen controller	0	4	operation, for the Trisen compressor	control group. The updated material	Wilson, Clifford P.	12/31/2006	Completed

PHA Page 2 of 3

PCOs and outside operators. Make training package available to any affected maintenance and tedhnical personnel.

Maintenance to review as well.

Section	n No	Section Des	cription						
62		Hot ISOMAX #4 & #5 CAT Feed Systems.							
Item	WhatIf	Deviation	A/C	SOE	RR	ABU Proposal Resolution	Owner	Due By	Status
7	16392	Human Factors	Consider field labeling of lines at the manifold locations and updating drawings to correspond with labels	S		Develop a simplified schematic of the Simplified drawing of C-440 bottoms feed system piping arrangement and label lines and valves in the field to match the schematic  Match the schematic  Splitter feeding Naphtha Splitter and a drawing to by-passing the Naphtha Splitter feeding directly to 5 Rheniformer has been developed. Drawings will be in the new EOM procedure for Loss of Naphtha Splitter. Updated 14 tab Emergency Procedure Loss of Naphtha Splitter. The lines in the field has been labeled.	Crowe, Stanley J.	6/1/2007	Completed

Section	n No	Section Descr	ription						
68		Wrap-Up Discuss	ion						
Item	WhatIf	Deviation	A/C	SOE RR	ABU Proposal	Resolution	Owner	Due By	Status
5	16394	Facility/Equipment Sitting	Verify that the control house still meets the requirements of API RP- 751 or make any modifications needed to bring it up to refinery standards for a SIP building	S 4	Investigate the possible solutions to the north/west door handicapped access door actuator causing the door to be left open. Investigate the system for rapidly shutting the control house ventilation system in the event of a toxic release and determine the reason for the exhaust louvers actuator being disconnected. Make any necessary modifications or repairs to bring the control house in to compliance with the refinery standards for a Shelter-in-Place building	the control house roof. The door to the control house can be shut and discussions have been had with the control house operators on the need to keep the door shut. Although the door can be safely kept shut, a latent condition addressing the door is currently open and options for a new non motorized control emechanism are being reviewed for	Capshaw, Michelle L.	12/31/2006	Completed

Back to top

Last Update: 4/10/2007

Page 3 of 3

© ZUU1 - ZUU3 CHEVIOH CORPORATION

Content Contact: <u>Karen, Draper (KAMR)</u> Technical Contact:<u>Pollepalli, Sanjeev (pols) Lee, Fred (FredWLee)</u>

Company Confidential Opco: <u>Richmond Refinery</u>